

YEAR: 2023 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Apr	646.3	-	646.3	Performed an annual condition inspection. This airframe has been inspected IAW the scope and detail of appendix D, part 43, and found to be in a condition for safe operation. Friday ^{AP} 3523
2024				
19 July	655.5	-	655.5	Greased 2x NG zircs. LPS2 all airframe control linkages pivot points and swivel points. Flushed gas colator. Re-topped right master brake cylinder with mil-h-5606 hyd. Fl. Cleaned air filter. Replaced right main LG tire with new, 28 psi. Inspected, cleaned, regrease RMLG bearing. Performed all ELT ✓'s - No battery corrosion, G-switch operation, etc. Batts due Dec 2025. Performed an annual condition inspection. This airframe has been inspected the scope & detail of appendix D, part 43 and found to be in a condition for safe operation. 12/20/25