

Wartungsübersicht / Maintenance record

Datum: Date:	Betriebsstunden: Engine hours / cycles:		Durchgeführte Arbeiten: Work performed:	Unterschrift & LFZ Wart Nr.: Signature & Licence no.:
	Gesamt: TSN:	seit letzter GÜ.: TSO:		
29 Mar 2023	646.1		Reclamped one leaky coolant connection and serviced the coolant overflow reservoir. Serviced the spark plugs and checked the gap. Added 1/2 quart engine oil. ^{Aero shell} sport 4 plus. IpDay AP 3523784.	
1 Apr 23	646.3		Replaced two exhaust springs. Boroscoped cylinders. Looked fine. Leakdown cyl. pressure test results as fol: 1) 79 2) 78 3) 79 4) 77 / 80 Performed an annual condition inspection. This engine has been inspected IAW the scope and detail of Appendix D, part 43 and found to be in a condition for safe operation. IpDay ^{AP} 3523784	
10 July 2024	655.5		Replaced one exhaust spring. Leakdown cylinder pressure test as follows: 1) 77 2) 78 3) 78 4) 77 / 80. Cleaned, inspected and regapped all plugs. Performed mech and pneumatic carb Sync. Performed an annual condition inspection. This engine has been inspected IAW the scope and detail of Appendix D Part 43 and found to be in a condition for safe operation. IpDay ^{AP} 3523784.	